

3 photos below show the current support for the lounge floor, by joists spanning between the ring beam, plus central support.



Photo 1 looking west



Photo 2 – looking south-west



Photo 3 – looking south